

B.O.Q For Annual Repair and Maintenance of CSD Tizu for 2009-10

Dimension(40.3 m x 7 mt x 2.46 mt)

ANNEXURE-A-5

SL.No	Particulars	Unit	Qty	Rate	Amount	Remarks
1	A water proof tarpauline cover of deck pump to be provided as reqd.	No	1	LS		
2	4nos. Wheels of deck pump to be supplied and fitting as reqd.	NO	4			
3	Suction rubber pipe (dia.2.5") alongwith footvalve for deck pump to be provided as reqd.	NO.	1	LS		
4	The wooden stand of A.C. has damaged. Same to be renewed with sal wood and also to provide a tarpauline cover for safety.	Copm.	Comp.	LS		
5	Spud lifting wire rope to be provided alongwith thimble in both side of rope (L-7 m, Dia-18mm) (Labour+material)	NO	2			
6	Wire rope (Steel core) for railing & tyre fender to be provided.(Dia.10mm L-100m)	Mts.	100			
7	Both side pannel board of G.E. are not working properly. Same to be checked and repair with renewal of spare-parts as reqd.					
a	Labour charges	NO	2			
b	Cost of spare- parts(Actual+10% basis)	As reqd.	As reqd	Ls		
8	Supd pulley guard to be provided as per direction of EIC.	No	2			
9	Ceiling cover of operator room is damaged. Same to be properly cropped and renewed with good quality cover as per direction of EIC.	Sq.mts.	8			
10	Door lock of operator room is defective. Same to be renewed with good quality lock as per direction of EIC.(labour+material)	NO	1	LS		
Grand Total						