

BOQ FOR AFLOAT REPAIR OF A.B.SIVALIK

SI No	Description	Quantity	RATE	AMOUNT
1	REPAIRE OF 3 PHASE AC TRANSFORMER & OUT PUT VOLTAGE LINE OF ALTERNATOR. TO BE CHECK & RECTIFY THE DEFECT.	4		
2	CHECKING OF ELECTRIC PANNEL BOARD AND RECTIFY THE DEFECT INCLUDING MATERIAL	COMP		
3	ALL 230 VOLT 3 PHASE A.C DISTRIBUTION PANNEL CHECKING & RECTIFY THE DEFECT	3		
4	EARTH FAULT IN 230 VOLT LINE IS DEFECTIVE & SAME TO BE RECTIFY	COMP		
5	THE EMERGENCY BATTERY CHARGER PANNEL TO BE CHECK & RECTIFY THE DEFECT INCLUDING SPARES	COMP		
6	PORT SIDE GEN SET COUPLING TO BE REPLACE WITH PROPER ALIGNMENT (
	(A) LABOUR CHARGE	COMP		
	(B) SPARES COST ACTUAL +10%			
7	FREASH WATER PUMP IS TO BE REPAIRED	1		
8	PORT SIDE GEN SET OUT PUT VOLTAGE & FREEQUENCY ADJUSTMENT AS PER LOAD	1		
9	COMPLETE OVERHAULING OF GEN SET ENGINE (STBD SIDE)			
	(A) LABOUR CHARGE	COMP		
	(B) SPARES COST ACTUAL +10%			
	TOTAL			