

BOQ for repair of out board engine of F.B.Falcon

SL. NO.	Description of work	Unit	Qty.	Rate	Amount
1	75 HP, out board engine, Make- Mariner is to be serviced including grinding/ machining of valves etc.				
a)	Labour charge	No.	1		
b)	Cost of spares (Actual + 10% basis, if required)	LS			
				TOTAL RS.	