

Sub: Notice Inviting Quotation for repair of the office vehicle no. WB-02M 5582 & WB 02L-0143 at Kolkata.

Sealed quotations are invited for repair of the office vehicle no. WB-02M 5582 & WB 02L-0143 at Kolkata as per the annexure enclosed herewith on the following terms and conditions.

TERMS & CONDITIONS

1. The price may be quoted including all the costs such as labour, taxes, transportation, etc. No other extra charges will be entertained.
2. The work shall be completed within 05 (Five) days from the date of placement of the vehicles at the work shop.
3. 100% payment will be made by cheque within fifteen days from date of receipt of the material and certification of the bill by the officer concerned after deducting the statutory dues.
4. The work shall be guaranteed for six months from the date of completion of work.
5. In case of delay in supply, liquidated damage @1% per week subject to a maximum of 5% will be charged.

The sealed quotation should reach to IWAI, Kolkata Office latest by 06.07.2009 at 1300 hrs. The sealed bids will be opened on the same day at 1500 hrs.

Encl: As stated.

(ARUN ROY)

Director

ANNEXURE -1

B.O.Q. FOR REPAIR OF TATA SUMO VEHICLE NO - WB - 02M - 5582				
SL.NO.	DESCRIPTION	QTY.	RATE	AMOUNT
1	Gear leave Kit removing, Replacement, adjustment & checking with spares	1Job		
2	Propeller shaft cross bearing 2nos, Yoke with teeth centre bearing rubber removing, replacement with Telco spares.	1Job		
3	Steering coloumn,cross bearing 2nos yoke with coloumn dust boot, Gear box dust boot cover removing & replacement of spares (Telco).	1Job		
4	Bonet lock,Bonet rubber buffer,B.light glass, Bulb removing & replacement with spares.	1Job		
5	Rubber matting, Fuel set &4nos of quarter matting.	1Job		
6	Machine shop charges for propeller shaft teeth steering,coloumn teeth cutting, New teeth Assy.Fitting & welding etc.	1Job		
7	Rear Lh full mud guard cutting near boarder with inside full core new welding & fearing with spares.	1Job		
8	Front Rh door body, inside floor corroded portion cutting, Patch repairing fairing with new sheet including welding charge.	1Job		
9	Front seat removing, seat frame electric welding reshaping & checking	1Job		
10	Painting on body work portion with 2k Paint & body floor white painting & polishing.	1Job		
11	Making & Fitting of new brass letter sign board Govt of India.	1Job		
12	Front seat handle lock Assy removing replacing & checking with spares.	1Job		
13	Mob oil, Mob Filter,D.Filter removing & replaced with material.	1Job		
	Total :			

ANNEXURE -2

B.O.Q. FOR REPAIR OF OFFICE JEEP WB - 02L - 0143				
SL.NO.	DESCRIPTION	QTY.	RATE	AMOUNT
1	Replacement of rubber Full matting at Floor (New)	1Job		
2	Replacement of 4nos of Quarter matting (New)	1Job		
3	Front seat repairing / Front & Rear seat cover (cloth) new making & Fitting.	1Job		
4	Mobil Filter,oil,Diesel Filter, air Filter new changing	1Job		
5	Servicing of the vehicle including of greasing.	1Job		
	Total :			