

IWAI/KOL/MM/12/Repair/ Dredging Unit, Farakka/07-08/2955 September 10, 2009

Sub : Notice Inviting Quotation for afloat repair of H.B. Nandadevi at Kolkata.

Sealed quotations are invited from experienced ship repairer for afloat repair of H.B. Nandadevi at Kolkata as per the B.O.Q. enclosed herewith on the following terms and conditions.

TERMS & CONDITIONS

1. The price may be quoted including all the costs such as labour, taxes, materials, transportation etc. Cost of spares will be paid extra wherever indicated in B.O.Q. No other extra charges will be entertained.
2. The work shall be completed within 10 (Ten) days from the date of receipt of the work order.
3. 90% payment will be made by cheque within fifteen days from date of completion of work and certification of the bill by the officer concerned after deducting the statutory dues. 10% will be paid after six months on successful performance of the work.
4. The work shall be guaranteed for six months from the date of completion of work.
5. In case of delay in completion, liquidated damage @1% per three days subject to a maximum of 5% will be charged.
6. IWAI reserves the right to reject any or all quotation.

The sealed quotation should reach to IWAI, Kolkata Office latest by 14.09.2009 at 15:00 hrs. The sealed bids will be opened on 14.09.2009 at 16:00 hrs. The "QUOTATION FOR AFLOAT REPAIR H.B. NANDADEVI AT KOLKATA" and N.I.Q. No. should be clearly written on the sealed envelope.

Encl: As stated.

(ARUN ROY)
Director.

B.O.Q. FOR AFLOAT REPAIR OF HB NANDADEVI					
Sl. No.	Description	Unit	Qty	Rate	Amount
A.	HULL				
B.	ACCOMODATION & WHEEL HOUSE / SUPERSTRUCTURE				
1	Fire Extinguisher to be Hyd. Pressure Tested in presence of IWT Surveyor & refilled. Testing certificate duly signed by IWT surveyor to be submitted in original.				
a)	Foam type - 9 kg.	No.	3		
b)	DCP - 5 Kg	No.	3		
c)	Water Co2	No.	2		
2	Repair of 2 nos. flush valves at toilet, arrest leakage of water from drain pipe (4" dia., 2' length) at Bathroom, repair of 4 nos. water tap at basin, fitting of new socket at sink outlet.	No.			
a)	Labour charges	job	1		
b)	Cost of spares (Actual +10% basis)				
3	Supply & fitting of Cover for Sintex tank (1000 Lt.)	No.	2		
4	Damaged / bend railing pipe to be straightened / renewal.	m.	2		
5	Additional Sea water line (1" dia., 20m length approx.) to be fabricated and fitted at Kitchen with all valves & fittings.	job	1		
6	Renewal of 1" dia. pipe at sea water line.	m.	3		
7	Door locks to be renewed.	No.	4		
8	Fire Hydrants to be serviced.	No.	2		
9	Emergency fire alarm system to be installed as per surveyor's recommendation.	job	1		
C.	MACHINERY				
10	Repair/Renewal of Exhaust pipe & Silencer of both side Generator Engine	job	2		
11	Servicing of sea water & fresh water pump				

a)	Labour charges	No.	2		
b)	Cost of spares (Actual +10% basis)				
12	Servicing of Engine Room blower				
a)	Labour charges	No.	2		
b)	Cost of spares (Actual +10% basis)				
D.	ELECTRICAL				
13	Repair of starter for fresh water pump motor including materials.	No.	1		
14	Servicing & repairing of Exhaust Fan of galley including materials.	No.	2		
15	Servicing & repairing of wall mounted fan at accommodation including materials.	No.	5		
16	Supply & fitting of main switch 3phase, 440Volt (as per sample).	No.	1		
17	Supply & fitting of double pole rotary switch (as per sample).	No.	2		
	GRAND TOTAL				

Director.